

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------|------------------------|--------------|-------------------------|--------------------------|
| Type of Inspection: | Annual | Date: | 9/5/2019 | Time: | 12:36 PM |
| Name of School Corporation: | SETON CATHOLIC SCHOOL | | | Corp ID: | D842 |
| Address of School Corporation: | 233 South 5th Street | | | | |
| City: | Richmond | Zip: | 47374 | County Number: | 89 |
| VIN: | 1GDHG31U131123835 | License Number: | SCS6 | Bus Number: | 6 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2003 | Make of Chassis: | Thomas Built Buses, Inc. |
| Bus Type: | A2 | Mileage: | 108030 | Year: | 2002 |
| Inspection Status: | R | Inspected By: | Jeremy Mason | PE: | 8139 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 23-1-3 | Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |
| 49-1-4 | Any reflector is missing, cracked, faded, or the wrong color. |
| 28-1-4 | The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction. |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.