

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	9/12/2019	Time:	11:10 AM		
Name of School Corporation:	FRANKTON-LAPEL COMM. SCHLS.			Corp ID:	485245		
Address of School Corporation:	7916 W 300 N						
City:	Anderson	Zip:	46011	County Number:	48		
VIN:	4DRBUAAP8FB028698		License Number:	8843	Bus Number:	24	
Make of Body:	IC Corporation	Year:	2013	Make of Chassis:	IC Corporation	Year:	2015
Bus Type:	C			Mileage:	53576		
Inspection Status:	O	Inspected By:	Jeremy Mason	PE:	8139		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
67-1-2	Rims are bent or loose

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-3	Any tire is flat

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.