

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Post-Crash Inspection	<b>Date:</b> 9/18/2019	<b>Time:</b> 9:07 AM
<b>Name of School Corporation:</b> PORTAGE TOWNSHIP SCHOOLS	<b>Corp ID:</b> 646550	
<b>Address of School Corporation:</b> 3300 Airport Rd		
<b>City:</b> Portage	<b>Zip:</b> 46368	<b>County Number:</b> 64
<b>VIN:</b> 4DRBUC8NXFB678262	<b>License Number:</b> 8616	<b>Bus Number:</b> 47
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2014	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2015	<b>Mileage:</b> 55606	<b>PE:</b> 7558
<b>Bus Type:</b> C	<b>Inspected By:</b> Tim Grayson	
<b>Inspection Status:</b> O		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
67-1-2	Rims are bent or loose

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-3	Any tire is flat

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**