REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		**Date:** 9/25/2019	**Time:**	10:10 AM
Name of School Corporation:	CROTHERSVILLE COMM. SCHOOLS			**Corp ID:**	363710
Address of School Corporation:	201 S Preston St				
City:	Crothersville	**Zip:**	47229	**County Number:**	36
VIN:	4UZABRDU48CZ46656		**License Number:** 31623	**Bus Number:**	5
Make of Body:	Thomas Built Buses, Inc.	**Year:** 2007	**Make of Chassis:** Freightliner	**Year:**	2008
Bus Type:	C		**Mileage:** 73146		
Inspection Status:	O	**Inspected By:**	Travis Coryea	**PE:**	5892

Violations - Rejected

Inspection Code	Description
50-1-1	The seat belt cutter is not located within the driver's view and reach
28-1-6	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.