

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 9/26/2019	<b>Time:</b> 9:01 AM
<b>Name of School Corporation:</b> INTERNATIONAL SCHOOL OF INDIANA	<b>Corp ID:</b> 49C677	
<b>Address of School Corporation:</b> 4330 N. Michigan Rd.		
<b>City:</b> Indianapolis	<b>Zip:</b> 46208	<b>County Number:</b> 49
<b>VIN:</b> 1GBJG31U861256607	<b>License Number:</b> B305AB	<b>Bus Number:</b> 8
<b>Make of Body:</b> Mid Bus, Inc.	<b>Year:</b> 2006	<b>Make of Chassis:</b> Chevrolet
<b>Year:</b> 2006		
<b>Bus Type:</b> C	<b>Mileage:</b> 41276	
<b>Inspection Status:</b> O	<b>Inspected By:</b> Jeff Kastenschmidt	<b>PE:</b> 5805

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-9	If the words "EMERGENCY EXIT" does not appear on the top or bottom of the window or directly above each emergency exit window on the inside of the bus
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
41-1-8	The interior storage container (MFSAB/Special Purpose Bus ONLY) is not securely fastened to the floor or does not have a cover with a positive fastening device.
43-1-8	Any required lettering is missing or faded.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
50-2-2	The seat belt cutter does not have a full width handgrip, with a protective blade to minimize risk

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**