REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	9/27/2019	**Time:**	12:26 PM
Name of School Corporation:	NORTHEAST SCHOOL CORPORATION					**Corp ID:**	777645
Address of School Corporation:	PO Box 493						
City:	Hymera		**Zip:**	47855		**County Number:**	77
VIN:	4DRBUAAN85B975978			**License Number:**	9843	**Bus Number:**	22
Make of Body:	IC Corporation	**Year:**	2003	**Make of Chassis:**	IC Corporation	**Year:**	2005
Bus Type:	C			**Mileage:**	137686		
Inspection Status:	R		**Inspected By:**	Byron Goodman		**PE:**	7008

Violations - Rejected

Inspection Code	Description
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.