

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 10/1/2019 **Time:** 7:46 PM
Name of School Corporation: NORTHEAST SCHOOL CORPORATION **Corp ID:** 777645
Address of School Corporation: PO Box 493
City: Hymera **Zip:** 47855 **County Number:** 77
VIN: 4DRBUAAN85B975978 **License Number:** 9843 **Bus Number:** 22
Make of Body: IC Corporation **Year:** 2003 **Make of Chassis:** IC Corporation **Year:** 2005
Bus Type: C **Mileage:** 138519
Inspection Status: O **Inspected By:** Byron Goodman **PE:** 7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
64-2-1	Any rear turn signal does not function properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.