

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	10/2/2019	Time:	8:43 AM		
Name of School Corporation:	HANOVER COMM. SCHOOL CORP.			Corp ID:	454580		
Address of School Corporation:	PO Box 645						
City:	Cedar Lake	Zip:	46303	County Number:	45		
VIN:	4DRBUAAN68B499587		License Number:	4952	Bus Number:	8	
Make of Body:	IC Corporation	Year:	2007	Make of Chassis:	IC Corporation	Year:	2008
Bus Type:	C		Mileage:	96874			
Inspection Status:	R	Inspected By:	Nathan Sherer	PE:	7029		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

### Violations - Out of Service

#### Inspection Code Description

#### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.