REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	10/2/2019	**Time:**	11:05 AM
Name of School Corporation:	SOUTH BEND COMM. SCHOOL CORP.			**Corp ID:**	717205
Address of School Corporation:	3003 N Bendix Dr				
City:	South Bend	**Zip:**	46601	**County Number:**	71
VIN:	4DRBUAAN57B408310	**License Number:**	30433	**Bus Number:**	194
Make of Body:	IC Corporation **Year:** 2007	**Make of Chassis:**	IC Corporation	**Year:**	2007
Bus Type:	C	**Mileage:**	154629		
Inspection Status:	O	**Inspected By:**	Travis Harrold	**PE:**	8022

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
65-2-1	Warning lights fail to operate correctly
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.