REPORT OF SCHOOL BUS INSPECTION

9:01 Type of Semi-Annual Date: 10/3/2019 **Time**: Inspection: AM MANCHESTER COMMUNITY SCHOOLS 858045 Name of School Corporation: Corp ID: **Address of School Corporation:** PO Box 308 County City: North Manchester Zip: 46962 85 Number: License VIN: 4UZABRDK28CZ54155 10279 **Bus Number:** 22 Number: Make of Thomas Built Buses, Year: 2007 Make of Body: Freightliner Year: 2008 Inc. Chassis: Bus Type: С Mileage: 122579

Inspected D. M. D.

Inspection Status: R By: Randy McPike PE: 7018

Violations - Rejected

Inspection Code Description

The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.