

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection Date: 10/9/2019 Time: 12:48 PM
Name of School Corporation: NORTHERN WELLS COMM. SCHOOLS Corp ID: 908435
Address of School Corporation:
City: Zip: County Number: 90
VIN: 4drbuc8n8gb107550 License Number: 10070 Bus Number: 36
Make of Body: IC Corporation Year: 2016 Make of Chassis: IC Corporation Year: 2015
Bus Type: C Mileage: 126877
Inspection Status: O Inspected By: Jamie Hotchkiss PE: 6458

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-2	The trash container is greater than a fourteen (14) quart capacity
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.