

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/9/2019	Time:	12:48 PM
Name of School Corporation:	NORTHERN WELLS COMM. SCHOOLS	Corp ID:	908435		
Address of School Corporation:					
City:	Zip:			County Number:	90
VIN:	4drbuc8n8gb107550	License Number:	10070	Bus Number:	36
Make of Body:	IC Corporation	Year:	2016	Make of Chassis:	IC Corporation
Year:			2015	Year:	2015
Bus Type:	C	Mileage:	126877		
Inspection Status:	O	Inspected By:	Jamie Hotchkiss	PE:	6458

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-2	The trash container is greater than a fourteen (14) quart capacity
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.