REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	10/9/2019	**Time:**	12:08 PM
Name of School Corporation:	NORTH NEWTON SCHOOL CORP.			**Corp ID:**	565945
Address of School Corporation:	PO Box 8				
City:	Morocco	**Zip:**	47963	**County Number:**	56
VIN:	1GB3G2BG3F1114953	**License Number:**	31096	**Bus Number:**	35
Make of Body:	Starcraft **Year:** 2015	**Make of Chassis:**	Chevrolet	**Year:**	2015
Bus Type:	C	**Mileage:**	130956		
Inspection Status:	O	**Inspected By:**	Nathan Sherer	**PE:**	7029

Violations - Rejected

Inspection Code	Description
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code	Description
53-2-5	“U” bolts are loose, broken, or missing
20-2-4	Emergency door is not securely fastened to body

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.