

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual	Date: 10/15/2019	Time: 9:27 AM	
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP	Corp ID: 131300		
Address of School Corporation: 5808 E Administration Rd			
City: Marengo	Zip: 47140	County Number: 13	
VIN: 4DRBUAAN78B499582	License Number: NB33	Bus Number: 33	
Make of Body: IC Corporation	Year: 2007	Make of Chassis: IC Corporation	Year: 2007
Bus Type: A1	Mileage: 126779		
Inspection Status: O	Inspected By: Mike Adams	PE: 7407	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**