

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/22/2019	Time:	6:01 PM
Name of School Corporation:	SOUTHWEST SULLIVAN SCHOOLS	Corp ID:	777715		
Address of School Corporation:	110 N Main St				
City:	Sullivan	Zip:	47882	County Number:	77
VIN:	1T7YT4C2451156674	License Number:	20582	Bus Number:	56
Make of Body:	Thomas Built Buses, Inc.	Year:	2004	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D	Mileage:	28735	Year:	2005
Inspection Status:	O	Inspected By:	Byron Goodman	PE:	7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.