## REPORT OF SCHOOL BUS INSPECTION

Type of 10:01 Semi-Annual 10/28/2019 Time: Date: Inspection: AM Name of School Corporation: PERU COMMUNITY SCHOOLS Corp ID: 525635 **Address of School Corporation:** 35 W 3rd St County City: Peru Zip: 46970 52 Number: License VIN: 4UZAAXCS74CL83412 13364 **Bus Number:** 63 Number: Make of Thomas Built Buses, Year: 2003 Freightliner Year: 2004 Make of Body: Inc. Chassis: **Bus Type:** С Mileage: 163155 Inspection Inspected R PE: 7018 Randy McPike Status: By:

## **Violations - Rejected**

## <u>Inspection Code</u> <u>Description</u>

13-1-1 Any clearance light is missing, cracked, faded, wrong color, or inoperative

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.