

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Re-Inspection	<b>Date:</b> 11/1/2019	<b>Time:</b> 9:40 AM
<b>Name of School Corporation:</b> M.S.D. MARTINSVILLE SCHOOLS	<b>Corp ID:</b> 555925	
<b>Address of School Corporation:</b> PO Box 1416		
<b>City:</b> Martinsville	<b>Zip:</b> 46151	<b>County Number:</b> 55
<b>VIN:</b> 4DRBUAAP95B978843	<b>License Number:</b> B327E	<b>Bus Number:</b> 29
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2004	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2005	<b>Mileage:</b> 209651	<b>PE:</b> 6473
<b>Bus Type:</b> C	<b>Inspected By:</b> Mark Raper	
<b>Inspection Status:</b> O		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-1	A dripping oil or fluid leak
22-1-3	There are loose motor mounts
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
31-2-1	Frame is deteriorated, cracked, broken or severely bent

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**