

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	11/6/2019	Time:	8:56 AM
Name of School Corporation:	SOUTH DEARBORN COMM. SCH. CORP	Corp ID:	151600		
Address of School Corporation:	6109 Squire Place				
City:	Aurora	Zip:	47001	County Number:	15
VIN:	4DRBRAAP73B952062	License Number:	B576L	Bus Number:	6
Make of Body:	IC Corporation	Year:	2002	Make of Chassis:	IC Corporation
Bus Type:	D	Mileage:	138061	Year:	2003
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-8	The interior storage container (MFSAB/Special Purpose Bus ONLY) is not securely fastened to the floor or does not have a cover with a positive fastening device.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.