REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	11/7/2019	**Time:**	1:09 PM
Name of School Corporation:	NEW ALBANY FLOYD CO. CONS SCH			**Corp ID:**	222400
Address of School Corporation:	4202 Charlestown Rd				
City:	New Albany	**Zip:**	47150	**County Number:**	22
VIN:	4DRBUC8P5HB407629	**License Number:**	11159	**Bus Number:**	17-6
Make of Body:	IC Corporation **Year:** 2017	**Make of Chassis:**	IC Corporation	**Year:**	2017
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	Troy Boyd	**PE:**	5171

Violations - Rejected

Inspection Code	Description
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.