

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 11/7/2019	Time: 1:09 PM
Name of School Corporation: NEW ALBANY FLOYD CO. CONS SCH	Corp ID: 222400	
Address of School Corporation: 4202 Charlestown Rd		
City: New Albany	Zip: 47150	County Number: 22
VIN: 4DRBUC8P5HB407629	License Number: 11159	Bus Number: 17-6
Make of Body: IC Corporation	Year: 2017	Make of Chassis: IC Corporation
Year: 2017	Mileage: Unknown	Year: 2017
Bus Type: C		
Inspection Status: O	Inspected By: Troy Boyd	PE: 5171

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.