

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	11/21/2019	Time:	9:58 AM		
Name of School Corporation:	CONCORD COMMUNITY SCHOOLS			Corp ID:	202270		
Address of School Corporation:	59040 Minuteman Way						
City:	Elkhart	Zip:	46517	County Number:	20		
VIN:	1BAKFCSA9JF339346		License Number:	17331	Bus Number:	25	
Make of Body:	Blue Bird Corporation	Year:	2017	Make of Chassis:	Blue Bird Corporation	Year:	2018
Bus Type:	C			Mileage:	49916		
Inspection Status:	O	Inspected By:	Wes Rowlader	PE:	7427		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-2	Step-well area is weakened
57-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)
41-1-3	There is loose or unprotected wiring in passenger area
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
34-1-1	Any headlight is inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
31-2-1	Frame is deteriorated, cracked, broken or severely bent
51-2-1	The service door does not open or close properly
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).
70-2-1	Any glass or glazing is broken through or missing
36-2-1	The latch mechanism is missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.