## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Semi-Annual			Date:	12/3/2019	Time:	10:23 AM
Name of School Corporation: MUI		MUN	INCIE COMMUNITY SCHOOLS			Corp ID:	181970
Address of School Corporation:		2501 N Oakwood					
City:	Muncie		Zip:	47304		County Number:	18
VIN:	1GBJC31U471202688	3		License Number:	73848	Bus Number:	3
Make of Body:	Collins Bus Corporation	Year:	2007	Make of Chassis:	Chevrolet	Year:	2007
Bus Type:				Mileage:	91095		
Inspection Status: O		Inspected By:	Jamie Hotchkiss		PE:	6458	

## Violations - Rejected

Inspection Code	Description
82-1-2	See Notes: Any defect inspector deems a violation not listed
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly

## Violations - Out of Service

Inspection <u>Code</u>	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
8-2-1	There is no brake certification, or the certification has expired or is not signed

## **Bus Type Description**