

## REPORT OF SCHOOL BUS INSPECTION

|                                |                          |                 |            |                  |                          |
|--------------------------------|--------------------------|-----------------|------------|------------------|--------------------------|
| Type of Inspection:            | Post-Crash Inspection    | Date:           | 12/6/2019  | Time:            | 9:56 AM                  |
| Name of School Corporation:    | M.S.D. WARREN TWP.       |                 |            | Corp ID:         | 495360                   |
| Address of School Corporation: | 9150 Rawles              |                 |            |                  |                          |
| City:                          | Indianapolis             | Zip:            | 46229      | County Number:   | 49                       |
| VIN:                           | 4UZAAXDC06CV83039        | License Number: | 21219      | Bus Number:      | 127                      |
| Make of Body:                  | Thomas Built Buses, Inc. | Year:           | 2005       | Make of Chassis: | Thomas Built Buses, Inc. |
| Bus Type:                      | C                        |                 |            | Mileage:         | 139426                   |
| Inspection Status:             | O                        | Inspected By:   | Jeff Stone | PE:              | 8184                     |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 24-1-2                 | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails |
| 72-1-3                 | See Notes: Any defect inspector deems a violation not listed  |
| 30-1-2                 | There are weak areas due to deterioration   |
| 22-1-1                 | A dripping oil or fluid leak  |
| 3-1-7                  | Battery compartment door is not securely fastened.  |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 32-2-1                 | There is fuel leaking from any point on in the fuel system  |
| 30-2-1                 | Floor sags or buckles substantially when stood upon. (NOTE: Check under bus to verify deterioration.) |

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.