REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Semi-Annual | | | Date: | 12/12/2019 | Time: | 7:31 PM |
|--------------------------------|---------------------------|----------------|--------------------|---------------------|-------------|-------------------|------------|
| Name of School C | • | AND | ERSON PREPA | ARATORY ACADE | MY | Corp ID: | 489790 |
| Address of School Corporation: | | 3205 W 25th St | | | | | |
| City: | Anderson | | Zip: | 46011 | | County Number: | 48 |
| VIN: | 1GBHG31RX11208447 | | License Number: | 5622 | Bus Number: | 1 | |
| Make of Body: | Girardin Minibus, Inc. | Year: | 2001 | Make of Chassis: | Chevrolet | Year: | 2001 |
| Bus Type: | A1 | | | Mileage: | 118219 | | |
| Inspection Status: | : 0 | | Inspected By: | Jeremy Mason | | PE: | 8139 |

Violations - Rejected

Inspection CodeDescription41-1-4There is debris in the bus. (needs cleaned/includes dirt)

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.

2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.