REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection		Date:	12/13/2019	Time:	10:31 AM
Name of Schoo Address of Sch	I Corporation: RIC	HLAND-BEAN 600 S Edge	N BLOSSOM C.S wood Dr	S.CORP	Corp ID:	535705
City:	Ellettsville	Zip:	47429		County Number:	53
VIN:	4UZABRDJ5ACAN3250		License Number:	B142D	Bus Number:	26
Make of Body:	Thomas Built Buses, Yea Inc.	r : 2009	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2010
Bus Type:	С		Mileage:	140494		
Inspection Status:	R	Inspected By:	Mark Raper		PE:	6473

Violations - Rejected

Inspection Code	Description
64-1-2	A lens is cracked, missing or wrong color
49-1-4	Any reflector is missing, cracked, faded, or the wrong color.
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.