REPORT OF SCHOOL BUS INSPECTION

Type of 9:20 Semi-Annual Time: Date: 12/13/2019 Inspection: AM Name of School Corporation: **BROWN"S BUS TRANSPORTION** Corp ID: 82008Z **Address of School Corporation:** 2120 Culverson County City: Evansville Zip: 47714 82 Number: License VIN: 1HVBBABP2YH307888 B467F **Bus Number:** M6 Number: Make of IC Blue Bird Year: 2000 Make of Body: Year: 2000 Corporation Corporation Chassis: Bus Type: С Mileage: 89663 Inspected PE: 7809 **Inspection Status:** R **Bradley Miller** By:

Violations - Rejected

<u>Inspection</u>	Description
Code	<u>Description</u>

50-1-2 The seat belt cutter is not secured using a positive fastening method.

Rims and wheels are painted any other color than black or gray. (Aluminum wheels may be of natural color) (MFSAB's are permitted to have factory wheels)

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.