

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                |                        |            |                         |                       |
|---------------------------------------|--------------------------------|------------------------|------------|-------------------------|-----------------------|
| <b>Type of Inspection:</b>            | Post-Crash Inspection          | <b>Date:</b>           | 12/16/2019 | <b>Time:</b>            | 10:51 AM              |
| <b>Name of School Corporation:</b>    | FRANKLIN COUNTY COMM. SCH CORP | <b>Corp ID:</b>        | 242475     |                         |                       |
| <b>Address of School Corporation:</b> | 225 E 10th St                  |                        |            |                         |                       |
| <b>City:</b>                          | Brookville                     | <b>Zip:</b>            | 47012      | <b>County Number:</b>   | 24                    |
| <b>VIN:</b>                           | 1BAKF CPA7CF285380             | <b>License Number:</b> | b210n      | <b>Bus Number:</b>      | 17                    |
| <b>Make of Body:</b>                  | Blue Bird Corporation          | <b>Year:</b>           | 2011       | <b>Make of Chassis:</b> | Blue Bird Corporation |
| <b>Bus Type:</b>                      | C                              | <b>Mileage:</b>        | 98838      |                         |                       |
| <b>Inspection Status:</b>             | O                              | <b>Inspected By:</b>   | Dan Elmore | <b>PE:</b>              | 5960                  |

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

#### Inspection Code

#### Description

|       |   |
|-------|---|
| 7-2-1 | There is no brake certification form the certification is expired or is not signed within the six-month requirement |
|-------|---|

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**