

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|--------------------------------|----------------------------|-----------------|--------------|------------------|--------------------------|
| Type of Inspection: | Re-Inspection | Date: | 12/19/2019 | Time: | 1:30 PM |
| Name of School Corporation: | NORTHEASTERN WAYNE SCHOOLS | | | Corp ID: | 898375 |
| Address of School Corporation: | 7295 US 27 N | | | | |
| City: | Fountain City | Zip: | 47341 | County Number: | 89 |
| VIN: | 1T7YT4B2051153935 | License Number: | 14063 | Bus Number: | 32 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2005 | Make of Chassis: | Thomas Built Buses, Inc. |
| Bus Type: | D | | | Mileage: | 132145 |
| Inspection Status: | R | Inspected By: | Jeremy Mason | PE: | 8139 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 28-1-2 | The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment." |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.