REPORT OF SCHOOL BUS INSPECTION

Type of 9:20 Re-Inspection 1/6/2020 Time: Date: Inspection: AM Name of School Corporation: UNION SCHOOL CORPORATION Corp ID: 686795 **Address of School Corporation:** 8707 W US 36 County City: Modoc Zip: 47358 68 Number: License VIN: 4UZAAXBW33CL65315 19084 **Bus Number:** Number: Make of Thomas Built Buses, Year: 2002 Freightliner Year: Make of Body: 2003 Inc. Chassis: **Bus Type:** С Mileage: 163335 Inspected PE: 6458 **Inspection Status:** R Jamie Hotchkiss By:

Violations - Rejected

Inspection Code	<u>Description</u>
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
50-1-1	The seat belt cutter is not located within the driver's view and reach

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.