REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection		**Date:** 1/6/2020	**Time:**	9:20 AM
Name of School Corporation:	UNION SCHOOL CORPORATION			**Corp ID:**	686795
Address of School Corporation:	8707 W US 36				
City:	Modoc	**Zip:**	47358	**County Number:**	68
VIN:	4UZAAXBW33CL65315		**License Number:** 19084	**Bus Number:**	3
Make of Body:	Thomas Built Buses, Inc.	**Year:** 2002	**Make of Chassis:** Freightliner	**Year:**	2003
Bus Type:	C		**Mileage:** 163335		
Inspection Status:	R	**Inspected By:**	Jamie Hotchkiss	**PE:**	6458

Violations - Rejected

Inspection Code	Description
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
50-1-1	The seat belt cutter is not located within the driver's view and reach

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.