

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 1/14/2020 **Time:** 9:18 AM
Name of School Corporation: NETTLE CREEK SCHOOL CORP. **Corp ID:** 898305
Address of School Corporation: 795 Baker Rd
City: Hagerstown **Zip:** 47346 **County Number:** 89
VIN: 4DRBUAAP5EB352075 **License Number:** NCSC5 **Bus Number:** 5
Make of Body: IC Corporation **Year:** 2012 **Make of Chassis:** IC Corporation **Year:** 2014
Bus Type: C **Mileage:** 47754
Inspection Status: O **Inspected By:** Jeremy Mason **PE:** 8139

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.