REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Annual | | | Date: | 1/15/2020 |) Time: | 8:49 AM |
|--------------------------------|-----------------------------|-----------------------------|------------------|---------------------|-----------|-------------------|------------|
| Name of School Corporation: | | EAST WASHINGTON SCHOOL CORF | | P. | Corp ID: | 888215 | |
| Address of School Corporation: | | 1050 N Eastern School Rd | | | | | |
| City: | Pekin | | Zip: | 47165 | | County Number: | 88 |
| VIN: | 1GBJG31UX71203442 | | | License Number: | 30551 | Bus Number: | 23 |
| Make of Body: | Thomas Built Buses, Inc. | Year | : 2008 | Make of Chassis: | Chevrolet | Year: | 2007 |
| Bus Type: | В | | | Mileage: | 174482 | | |
| Inspection Status | :: A | | Inspected By: | Troy Boyd | | PE: | 5171 |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.