## REPORT OF SCHOOL BUS INSPECTION

Time: Type of Inspection: Annual Date: 2/5/2020 9:04 AM

Name of School Corporation: NORTH LAWRENCE COMM. SCHOOLS

Corp ID: 475075

**Address of School Corporation:** 595 Stars Blvd

City: Bedford Zip: 47421 County Number: 47 VIN: 1HVBBAAN3WH570856 **Bus Number:** License Number: 16626 A10 Make of Body: AmTran Year: 1998 Make of Chassis: IC Corporation Year: 1998

**Bus Type:** C Mileage: 95986

0 Inspected By: Travis Coryea PE: **Inspection Status:** 5892

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection** Description Code

Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at 7-2-4 other than a proper connection).

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.