## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:2/12/2020Time:9:38 AMName of School Corporation:NORTH LAWRENCE COMM. SCHOOLSCorp ID:475075

Address of School Corporation: 595 Stars Blvd

City:BedfordZip:47421County Number:47VIN:4DRBUAAN3DB311988License Number:5033Bus Number:A42Make of Body:IC Corporation Year:2012Make of Chassis:IC Corporation Year:2013

Bus Type: C Mileage: 70718

Inspection Status: O Inspected By: Travis Coryea PE: 5892

## Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

46-1-3 Any required padding is missing

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.