REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection		Date:	2/12/2020	Time:	1:15 PM	
Name of School Co	prporation: DUN	ELAND SCHOO	L CORPORATION		Corp ID:	646470
Address of School	Corporation:	601 W MORGA	AN AVE			
City:	Chesterton	Zip:	46304		County Number:	64
VIN:	4DRBUC8N0KB228	145	License Number:	22227	Bus Number:	6
Make of Body:	IC Corporation Year:	2018	Make of Chassis:	IC Corporation	Year:	2019
Bus Type:	С		Mileage:	19001		
Inspection Status:	А	Inspected By:	Tim Grayson		PE:	7558

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.