REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	3/11/2020	**Time:**	8:38 AM
Name of School Corporation:		TIPTON COMMUNITY SCHOOL CORP.				**Corp ID:**	807945
Address of School Corporation:		1051 S. Main St.					
City:	Tipton	**Zip:**	46072			**County Number:**	80
VIN:	1T7YT4E2191115275			**License Number:**	30978	**Bus Number:**	47
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2008	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2009
Bus Type:	D			**Mileage:**	54880		
Inspection Status:	O	**Inspected By:**	Randy McPike			**PE:**	7018

Violations - Rejected

Inspection Code	Description
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1”x5yd, 1 blunt scissor, 6 3x3” gauze pads (sterile), 4 2”x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

Inspection Code	Description
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.