

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 3/12/2020	<b>Time:</b> 12:09 PM
<b>Name of School Corporation:</b> OUR LADY OF GREENWOOD	<b>Corp ID:</b> 41B353	
<b>Address of School Corporation:</b> 399 S Meridian St		
<b>City:</b> Greenwood	<b>Zip:</b> 46142	<b>County Number:</b> 41
<b>VIN:</b> 1GBL7T1C91J508955	<b>License Number:</b>	<b>Bus Number:</b> 101
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2001	<b>Make of Chassis:</b> Chevrolet
<b>Year:</b> 2002		
<b>Bus Type:</b> B	<b>Mileage:</b> 118063	
<b>Inspection Status:</b> R	<b>Inspected By:</b> Jeff Kastenschmidt	<b>PE:</b> 5805

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-1	Any lens is cracked, missing, faded or of the wrong color
29-1-7	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**