

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/10/2020	Time:	11:47 AM
Name of School Corporation:	JAY SCHOOL CORPORATION			Corp ID:	383945
Address of School Corporation:	PO Box 1239				
City:	Portland	Zip:	47371	County Number:	38
VIN:	4UZABRDUX9CAG9140	License Number:	32042	Bus Number:	62
Make of Body:	Thomas Built Buses, Inc.	Year:	2008	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	C	Mileage:	213110	Year:	2009
Inspection Status:	O	Inspected By:	Jamie Hotchkiss	PE:	6458

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.