

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection      Date: 3/13/2020      Time: 9:20 AM  
Name of School Corporation: NORTHERN WELLS COMM. SCHOOLS      Corp ID: 908435  
Address of School Corporation:  
City:      Zip:      County Number: 90  
VIN: 4DRBUSKN5EB758912      License Number: 5876      Bus Number: 29  
Make of Body: IC Corporation      Year: 2013      Make of Chassis: IC Corporation      Year: 2014  
Bus Type: C      Mileage: 213173  
Inspection Status: O      Inspected By: Jamie Hotchkiss      PE: 6458

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.