

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 3/13/2020	Time: 9:20 AM
Name of School Corporation: NORTHERN WELLS COMM. SCHOOLS	Corp ID: 908435	
Address of School Corporation:		
City:	Zip:	County Number: 90
VIN: 4DRBUSKN5EB758912	License Number: 5876	Bus Number: 29
Make of Body: IC Corporation	Year: 2013	Make of Chassis: IC Corporation
Year: 2014	Mileage: 213173	
Bus Type: C	Inspected By: Jamie Hotchkiss	PE: 6458
Inspection Status: O		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.