REPORT OF SCHOOL BUS INSPECTION

Type of Annual Date: 3/16/2020 Time: 11:28 AM

Name of School Corporation: BLACKFORD COUNTY SCHOOLS Corp ID: 50515

Address of School Corporation: 668 W CR 200S

City:Hartford CityZip:47348County Number:5VIN:4DRBUC8N8KB292000License Number:22500Bus Number:218Make of Body:IC Corporation Year:2018Make of Chassis:IC Corporation Year:2019

Bus Type: C Mileage: 29722

Inspection Status: O Inspected By: Jamie Hotchkiss PE: 6458

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

52-1-2 Any shock absorber is leaking fluid

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.