

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 3/26/2020 Time: 9:48 AM
Name of School Corporation: PERU COMMUNITY SCHOOLS Corp ID: 525635
Address of School Corporation: 35 W 3rd St
City: Peru Zip: 46970 County Number: 52
VIN: 1GB6G3AGXA1168294 License Number: 83999 Bus Number: Tiger2
Make of Body: Starcraft Year: 2010 Make of Chassis: Chevrolet Year: 2010
Bus Type: A2 Mileage: 92996
Inspection Status: R Inspected By: Randy McPike PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
24-1-5	Any paint is badly faded or peeling

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.