## **REPORT OF SCHOOL BUS INSPECTION**

| Type of<br>Inspection:  | Annual                   |   | Date:               | 4/8/2020                 | Time:             | 9:07<br>AM |
|---|--------------------------|---|---------------------|--------------------------|-------------------|------------|
| Name of School Corporation:<br>Address of School Corporation: |                          | NORTH JUDSON-SAN PIERRE SCH CO<br>801 Campbell Dr |                     |                          | Corp ID:          | 757515     |
| City:   | North Judson             | Zip:  | 46366               |                          | County<br>Number: | 75         |
| VIN:  | 1BAKGCPH9AF270225        |   | License<br>Number:  | 10659                    | Bus Number:       | 19         |
| Make of Body:   | Blue Bird<br>Corporation | Year: 2009  | Make of<br>Chassis: | Blue Bird<br>Corporation | Year:             | 2010       |
| Bus Type:   | С                        |   | Mileage:            | 84278                    |                   |            |
| Inspection<br>Status:   | A                        | Inspected<br>By:                                  | Nathan Shere        | er                       | PE:               | 7029       |

## **Violations - Rejected**

## Inspection Code Description

Violations - Out of Service

Inspection Code Description

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.