

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|---------------------------|------------------------|--------------|-------------------------|----------------|
| Type of Inspection: | Annual | Date: | 4/8/2020 | Time: | 10:24 AM |
| Name of School Corporation: | KOKOMO SCHOOL CORPORATION | | | Corp ID: | 343500 |
| Address of School Corporation: | 620 W Deffenbaugh | | | | |
| City: | Kokomo | Zip: | 46901 | County Number: | 34 |
| VIN: | 4DRBUC8N0HB466618 | License Number: | 19106 | Bus Number: | 234 |
| Make of Body: | IC Corporation | Year: | 2016 | Make of Chassis: | IC Corporation |
| | | Year: | | Year: | 2017 |
| Bus Type: | C | Mileage: | 51965 | | |
| Inspection Status: | R | Inspected By: | Randy McPike | PE: | 7018 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 90-1-4 | A trash container is located rearmost seats of a rear engine bus or at the back of a wheel chair equipped bus |
| 17-1-1 | Any dome light is inoperative |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.