REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Spot Checks	**Date:**	4/23/2020	**Time:**	8:47 AM
Name of School Corporation:	PRIMROSE SCHOOL OF W. FISHERS			**Corp ID:**	290004
Address of School Corporation:	12609 Parkside Dr.				
City:	Fishers	**Zip:**	46038	**County Number:**	29
VIN:	1GBHG31C681181818	**License Number:**	B930AC	**Bus Number:**	2
Make of Body:	Chevrolet **Year:** 2008	**Make of Chassis:**	Chevrolet	**Year:**	2008
Bus Type:	A1	**Mileage:**	46113		
Inspection Status:	O	**Inspected By:**	Jeff Kastenschmidt	**PE:**	5805

Violations - Rejected

Inspection Code	Description
62-1-10	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
11-2-1	A trailer hitch is attached
8-2-1	There is no brake certification, or the certification has expired or is not signed

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**