

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Spot Checks Date: 4/23/2020 Time: 8:47 AM
Name of School Corporation: PRIMROSE SCHOOL OF W. FISHERS Corp ID: 290004
Address of School Corporation: 12609 Parkside Dr.
City: Fishers Zip: 46038 County Number: 29
VIN: 1GBHG31C681181818 License Number: B930AC Bus Number: 2
Make of Body: Chevrolet Year: 2008 Make of Chassis: Chevrolet Year: 2008
Bus Type: A1 Mileage: 46113
Inspection Status: O Inspected By: Jeff Kastenschmidt PE: 5805

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-10	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
11-2-1	A trailer hitch is attached
8-2-1	There is no brake certification, or the certification has expired or is not signed

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.