

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                            |                        |            |                         |           |
|---------------------------------------|----------------------------|------------------------|------------|-------------------------|-----------|
| <b>Type of Inspection:</b>            | Re-Inspection              | <b>Date:</b>           | 4/23/2020  | <b>Time:</b>            | 9:43 AM   |
| <b>Name of School Corporation:</b>    | BLOOMFIELD SCHOOL DISTRICT | <b>Corp ID:</b>        | 282920     |                         |           |
| <b>Address of School Corporation:</b> | PO Box 266                 |                        |            |                         |           |
| <b>City:</b>                          | Bloomfield                 | <b>Zip:</b>            | 47424      | <b>County Number:</b>   | 28        |
| <b>VIN:</b>                           | 1GB3G2BG9E1204946          | <b>License Number:</b> | 28609      | <b>Bus Number:</b>      | 6corp     |
| <b>Make of Body:</b>                  | Thomas Built Buses, Inc.   | <b>Year:</b>           | 2014       | <b>Make of Chassis:</b> | Chevrolet |
| <b>Bus Type:</b>                      |                            | <b>Mileage:</b>        | 49343      | <b>Year:</b>            | 2014      |
| <b>Inspection Status:</b>             | R                          | <b>Inspected By:</b>   | Mark Raper | <b>PE:</b>              | 6473      |

**Violations - Rejected**

| <u>Inspection Code</u> | <u>Description</u>            |
|------------------------|-------------------------------|
| 17-1-1                 | Any dome light is inoperative |

**Violations - Out of Service**

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

**Bus Type Description**