REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	4/30/2020	Time:	10:05 AM
Name of School Corporation: Address of School Corporation:		OAK HILL UNITED SCHOOL CORP. PO Box 550		Corp ID:	525625	
City:	Converse	Zip:	46919		County Number:	52
VIN:	1BAKGCEA3JF33	7231	License Number:	19630	Bus Number:	9
Make of Body:	Blue Bird Corporation	Year: 2016	Make of Chassis:	Blue Bird Corporation	Year:	2018
Bus Type:	С		Mileage:	55014		
Inspection Status:	R	Inspected By:	d Randy McPike	9	PE:	7018

Violations - Rejected

Inspection CodeDescription41-1-4There is debris in the bus. (needs cleaned/includes dirt)

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.