

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	4/30/2020	Time:	10:16 AM
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625
Address of School Corporation:	PO Box 550				
City:	Converse	Zip:	46919	County Number:	52
VIN:	4UZABRDTXCCBA1230	License Number:	1112	Bus Number:	10
Make of Body:	Thomas Built Buses, Inc.	Year:	2011	Make of Chassis:	Freightliner
Bus Type:	C	Year:	2012	Mileage:	96329
Inspection Status:	R	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.