## **REPORT OF SCHOOL BUS INSPECTION**

| Type of<br>Inspection:         | Annual                      |                           |                    | Date:               | 5/6/2020     | Time:             | 11:42<br>AM |
|--------------------------------|-----------------------------|---------------------------|--------------------|---------------------|--------------|-------------------|-------------|
| Name of School Corporation:    |                             | ELKHART COMMUNITY SCHOOLS |                    |                     | Corp ID:     | 202305            |             |
| Address of School Corporation: |                             |                           | 2720 California Rd |                     |              |                   |             |
| City:                          | Elkhart                     |                           | Zip:               | 46514               |              | County<br>Number: | 20          |
| VIN:                           | 4UZAAXCS57CW43309           |                           | License<br>Number: | 1847                | Bus Number:  | 7                 |             |
| Make of Body:                  | Thomas Built Buses,<br>Inc. | Year:                     | 2005               | Make of<br>Chassis: | Freightliner | Year:             | 2007        |
| Bus Type:                      | С                           |                           |                    | Mileage:            | 116642       |                   |             |
| Inspection<br>Status:          | A                           |                           | Inspected<br>By:   | Wes Rowlader        |              | PE:               | 7427        |

## **Violations - Rejected**

Inspection Code Description

Violations - Out of Service

Inspection Code Description

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.